

IN THE SPECIFICATION:

Delete Paragraph 10 of the specification, beginning with "In accordance with this arrangement", and replace it with the following substitute paragraph, in which changes are indicated by underlining, strikethrough, or double brackets:

[0010] In accordance with this arrangement, since the voltage applied to the actuator is duty-controlled in each of the large number of consecutive micro time regions set in a cycle of out and back movement of the movable member, the current passing through the actuator when the movable member has moved back can reliably be made zero.

Delete Paragraph 20 of the specification, beginning with "In accordance with this arrangement", and replace it with the following substitute paragraph, in which changes are indicated by underlining, strikethrough, or double brackets:

[0020] An active vibration isolation support system M shown in FIGS. 1 to 4 is provided for elastically supporting an engine E on a vehicle body frame F of an automobile. The [[s]]system is controlled by an electronic control unit U to which are connected an engine rotational speed sensor Sa for detecting the engine rotational speed, a load sensor Sb for detecting the load that is input to the active vibration isolation support system M, an acceleration sensor Sc for detecting the acceleration acting on the engine E, and a lift sensor Sd for detecting the amount of lift of a movable member 20 of an actuator 29, which will be described below.